

Demo Hire (hire package)

Demo Lift Co DS-12 scissor (DEMO-HR02)

Plant ID: DEMO-HR02

Machine records, generated 16/10/2026, 17:31. A point-in-time copy: scan the QR code on the machine for the live record.

CHECK BEFORE USE

- 1 open defect: 1 minor

Last prestart: today 02:40 by Alex.

Every operator must complete their own prestart before using the machine, even if one was done today.

This shows what the records say. As of 16/10/2026, 17:31.

Service history

Date	What was done
12/09/2026	3-monthly service and safety inspection
13/06/2026	3-monthly service and safety inspection
29/04/2026	Annual inspection
14/03/2026	3-monthly service and safety inspection

Recent prestarts

When	Operator	Reading	Result
16/10/2026, 02:40	Alex	467.0	Pass
15/10/2026, 06:22	Sam	464.9	Pass
14/10/2026, 06:15	Jordan	461.8	Pass
13/10/2026, 06:36	Alex	459.2	Pass
12/10/2026, 06:29	Sam	457.1	Pass
11/10/2026, 06:22	Jordan	454.0	Pass
10/10/2026, 06:15	Alex	451.4	Pass
09/10/2026, 06:36	Sam	449.3	Pass
08/10/2026, 06:29	Jordan	446.2	Pass
07/10/2026, 06:22	Alex	443.6	Pass

Risk assessment and SWMS

Document	Details
Risk assessment	Risk assessment, Demo Lift Co DS-12 scissor DEMO-HR02 (demo) (version 1). Signed off 06/10/2026. Planned review 06/10/2027. https://demo-hire.deadsetsafety.com.au/m/rPOCPOUzdvbZnL3VvIW4SoFc47URUg5TS2loFNYFYNw/safety/2.pdf